

Firmware Version	Date Implemented	Firmware Notes	Unit Affected V3
3.0.04	3/29/2021	Changed the production self-test to reflect new fuse settings that are programmed at the factory. These new fuse settings prevent a rare issue where FW (but not bootloader) is lost due to a brownout event. A brownout event is when the battery voltage dips below the safe operating limit for the given processor speed. A brownout event can happen if the V3 is left on and the battery dies, but only rarely is the FW lost or corrupted.	X
3.0.03	NA	Updates display to transfer archived shot strings and active series shot strings for XFR.	X
2.1.04	NA	Changed the default battery to CR123A, for the military kits.	X
2.1.03	NA	Fixes issue with 1.009 and allows use of the XFR cable to transfer ACTIVE shot series only. No Archive series transfer.	X
1.009	NA	Original FW. Outdated. Potential to cause error messages. You cannot use the XFR cable with this firmware. Recommend updating firmware immediately.	X